

# PRE-COMPLETION INSPECTION CHECKLIST

Website: www.homesnag.co.uk email: info@homesnag.co.uk Tel: 0203 7933588

EDITION



### CONTENTS

01	INTRODUCTION
02	SCOPE OF SURVEY
03	TERMINOLOGY
04	G U I D A N C E
05	PROPERTY DETAILS
06	SURVEYOR DETAILS
07	ANY URGENT ISSUES
08	PAINTWORK RATING
09	CHECKS CARRIED OUT
10	VIDEO OF ANY ISSUES

### **External**

Grounds	p1-2
Garage	p3-4
Roof	
Boundary & Services	
Elevations	
Windows & Doors	

### Internal

Hallway WC	p13-14 p15-17
Living room	
Dining Area/Room	p20-21
Kitchen	p22-24
Utility	p25-27
Stairs & Landing	p28-29
Master Bed	. p30-31
Master Ensuite	p32-34
Bed 2	p35-36
Bed 3	p37-38
Bed 4	p39-40
Bathroom	p41-43
Airing Cupboard	p44-45
Loft	. p46-47
Heating	
Alarms (etc)	p48
Any Other Room	p49



Trading Names: HomeSnag North Limited, HomeSnag Mid East Limited, HomeSnag South East LImited. HomeSnag South West Limited. All trading under HomeSnag © - a registered trademark





### INTRODUCTION

This Pre-Completion survey is a non-invasive assessment of fixtures, fittings and services. Our surveyor carries out checks comparable with normal daily use to provide a simple checklist that has been determined by the NHQB (New Homes Quality Board).

Unlike a traditional snagging survey, we are unable to use specialist equipment to identify and capture issues. External checks will be an inspection from ground level and internally only basic tools such as a spirit level and socket tester are used. This is to abide by the instructions of the NHQB. Should you require a thorough snagging survey after moving in, you can book an inspection easily online or by calling our office.



### SCOPE OF SURVEY

The format of this pre-completion survey has been specifically designed by the NHQB (New Homes Quality Board). Split into internal and external requirements, its purpose is to provide the homeowner with a "finishing checklist" in haste of completion.

According to the requirements set out by the NHQB, this survey has been carried out by a suitably qualified inspector that is a member of a recognised professional association. As a company, HomeSnag is a well-established nationwide snagging company that holds adequate professional indemnity insurance. All our surveyors only work with their competency. We are regulated by RICS, and are members of the RPSA and Property Ombudsman.

This survey is not a structural building survey and we are not to be held liable for any issues that may occur after our inspection and/or outside the scope of the guidance laid out by the NHQB.

As part of this survey, we will endeavour to inspect all accessible parts of the property but we do not move furniture, tradesmans tools, floor coverings etc.

We are raising issues on behalf of the homeowner or client that is paying for our service but will remain impartial when raising issues that we feel are justified in the aim of maintaining our company's integrity.

As new-build houses undergo the settlement process over the first few years, issues will likely occur such as shrinkage cracks (inside and externally), nail pops, creaking of floorboards and misalignment of doors. Such issues are common and if they occur after our visit they will need to be raised with the developer directly.

We also recommend inspecting your property in varying environmental conditions such as heavy rainfall or alternative lighting to check for issues that may otherwise not be evident on the day the report was carried out.




Registered Address: James House, Stonecross Business Park, Yew Tree Way, Warrington, Cheshire, WA3 3JD

Trading Names: HomeSnag North Limited, HomeSnag Mid East Limited, HomeSnag South East LImited. HomeSnag South West Limited. All trading under HomeSnag © - a registered trademark

<u>website:</u> www.homesnag.co.uk <u>tel:</u> 0203 7933588 <u>email:</u> info@homesnag.co.uk



### TERMINOLOGY



"Architrave" - (also known as "arc") is the decorative finish around doorframes

"Aco" - a channel drain typically found in driveways

"Banding" - Typically in reference to brickwork or roof coverings, different batches will provide slightly different appearance and so should be mixed to avoid obvious patches that clash

"Brickslot" - A type of channel drain typically found in front of doorways

"Efflorescence" - A white appearance on brickwork. It occurs when moisture pulls the salt out of the building material. It is essential for bricks to be covered and left in pallets to minimise this being an eye sore across the whole of the building.

"Plastic Surgeon" - A specialist trade also known as Magic Man. They are able to repair damaged units unless high-gloss, metal or glass.

"Plumb" - whether something is a vertical upright. Being "out of plumb" means that it deviates from this.

"Stringer" - (also called 'string' or 'stringer board') is the housing on either side of a flight of stairs, into which the treads and risers are fixed. A staircase will have two stringers, one on either side of the steps.



Registered Address: James House, Stonecross Business Park, Yew Tree Way, Warrington, Cheshire, WA3 3JE

**Trading Names:** 

HomeSnag North Limited, HomeSnag Mid East Limited, HomeSnag South East LImited. HomeSnag South West Limited. All trading under HomeSnag © - a registered trademark

website: www.homesnag.co.uk - <u>tel:</u> 0203 7933588 - <u>email:</u> info@homesnag.co.uk



### G U I D A N C E

The NHQB v1 Pre Completion Inspection Checklist specifies that we (as suitably qualified inspectors) must not deviate from the checks specified in their guidance. Some terminologies used in this report have therefore been restricted to specific wording and choices of issues are restricted.

Generally speaking, the NHQB guidance requires aspects of the property to perform as intended and for the workmanship to be neat and tidy and to a plumb/level appearance (by eye). When we are determining subjectively whether it is a snag or not, we rely on our experience (our "professional eye" as it were) and whether it can/should be improved.

The guidance of the NHQB otherwise specifies:

- External walls should be inspected in daylight from a distance of 10m
- Internal ceiling, wall paintwork finishes, mastic and sealing should be inspected in daylight from a distance of 2m and not shining a light on the surface.
- Cupboards, wardrobe, surfaces and fitted furniture (inc. kitchens and bathrooms) should be inspected in daylight from a distance of 0.5m
- Glazing should be inspected in daylight from a distance of 2m (or 3m if laminated or toughened glass) and not shining a light on the surface. Fine scratches less than 25mm and bubbles or blisters if not obtrusive or bunched are acceptable
- All checks on the property will be visual from the ground
- Loft spaces and eaves are only inspected where safely accessible\*

\*Our surveyors to carry out a head and shoulders inspection from the loft hatch on this basis.

We will typically only raise a couple of example pictures of reoccurring issues rather than photographing every single snag in order for this report to be concise and remain within the scope of this being a checklist. Likewise our inspector will prioritise the main issues being added, so minor snags may be discounted. Conversely, there may be technical issues (according to guidance set by the likes of the NHBC and Building Regulations etc) that our inspector finds but is unable to raise within the scope of this checklist.

Limitations are important to note as they may explain or override aspects checked. For example if the water was off at the time of the inspection, we will be only able to carry out a visual check on the taps only. We may have specified it Meets Standards, but this relating to the visual aspect only.

Works Ongoing likewise will explain why certain aspects may not Meet Standards beyond what is presented to the surveyor in this checklist.

Urgent Issues will only include those of 'common sense' such as if we see signs of moisture internally or a hazard such as an exposed wire. We are otherwise unable to raise important issues outside the scope of this report.



Registered Address: James House, Stonecross Business Park, Yew Tree Way, Warrington, Cheshire, WA3 3JD

Trading Names: HomeSnag North Limited, HomeSnag Mid East Limited, HomeSnag South East LImited. HomeSnag South West Limited. All trading under HomeSnag © - a registered trademark

<u>website:</u> www.homesnag.co.uk <u>tel:</u> 0203 7933588 <u>email:</u> info@homesnag.co.uk



### PROPERTY DETAILS



**Example Property** 

05/07/23

The weather at the time of the survey was dry but overcast. We advise that the house is inspected during and after rainfall to check for rainwater goods, drainage etc. Also scratches in glass may be more obvious in sunny weather



### SURVEYOR DETAILS



Alex is an assocRICS surveyor having completed the SAVA Level 6 Diploma in Residential Surveying. A member of the RPSA, he has a NVLQ level 3 Domestic Energy and a diploma in Applied Building Thermography

Email: alex@homesnag.co.uk



Registered Address: James House, Stonecross Business Park, Yew Tree Way, Warrington, Cheshire, WA3 3JD

HomeSnag North Limited, HomeSnag Mid East Limited, HomeSnag South East LImited. HomeSnag South West Limited. All trading under HomeSnag © - a registered trademark

<u>website:</u> www.homesnag.co.uk - <u>tel:</u> 0203 7933588 - <u>email:</u> info@homesnag.co.uk



07 ANY URGENT ISSUES				
$\overline{}$				
GROUNDS				
GARAGE				
ROOF				
BOUND. & SERV				
ELEVATIONS				
WINDOWS & DOORS				
HALLWAY				
WC				
LIVING ROOM				
DINING AREA				
KITCHEN	Ideally there should be double check valve on pipe incase the appliance is change to one without one			
UTILITY	No double check valve			
STAIRS LANDING	Top nosing not level, trip hazard			
MASTER BED				
ENSUITE				
BED 2				
BED 3				
BATHROOM	Shower head reaches toilet, backflow risk			
CUPBOARD				
LOFT				
HEATING				





### PAINTWORK RATING

HALLWAY	Good: the plasterwork / paintwork was overall good, just a couple of areas to address. Meets Standards ✓	STAIRCASE LANDING	Fair: The paintwork / plaster has several areas still to patch / touch up so does not meet standards.
wc	Good: the plasterwork / paintwork was overall good, just a couple of areas to address. Meets Standards ✓	MASTER BED	Good: the plasterwork / paintwork was overall good, just a couple of areas to address. Meets Standards 🗸
LIVING ROOM	Good: the plasterwork / paintwork was overall good, just a couple of areas to address. Meets Standards ✓	ENSUITE	Fair: The paintwork / plaster has several areas still to patch / touch up so does not meet standards.
DINING AREA	Good: the plasterwork / paintwork was overall good, just a couple of areas to address. Meets Standards ✓	BED 2	Good: the plasterwork / paintwork was overall good, just a couple of areas to address. Meets Standards 🗸
KITCHEN	Paintwork is either ongoing or a poor standard with numerous areas to address. Does not meet standards	BED 3	Excellent: The plasterwork / paintwork was deemed to be exemplary. Meets standards 🗸
UTILITY	Fair: The paintwork / plaster has several areas still to patch / touch up so does not meet standards.	BED 4	Good: the plasterwork / paintwork was overall good, just a couple of areas to address. Meets Standards 🗸
		BATHROOM	Fair: The paintwork / plaster has several areas still to patch / touch up so does not meet standards.
		CUPBOARD	Good: the plasterwork / paintwork was overall good, just a couple of areas to address. Meets Standards ✓



Trading Names: HomeSnag North Limited, HomeSnag Mid East Limited, HomeSnag South East LImited. HomeSnag South West Limited. All trading under HomeSnag © - a registered trademark



### CHECKS CARRIED OUT

Below are a few photos showing some of the checks carried out which include:

- checks on the sockets using a tester plug
- (starting) a cycle on appliances to check for connection
- running the bath / shower to check for leaks
- inspection chamber check to indicate any blockages
- loft inspection (head and shoulders check from loft hatch)
- Roof check (from ground level)



Please note that in some instances we'll be unable to carry out checks due to limitations or they don't apply so sections above may be blank.



This section provides links to any videos taken during the inspection. Videos may have been taken to help explain an issue such as a noise or an urgent matter

If the below boxes are blank then no videos were taken during the inspection





Registered Address: James House, Stonecross Business Park, Yew Tree Way, Warrington, Cheshire, WA3 3JD

Trading Names: HomeSnag North Limited, HomeSnag Mid East Limited, HomeSnag South East LImited. HomeSnag South West Limited. All trading under HomeSnag © - a registered trademark

<u>website:</u> www.homesnag.co.uk - <u>tel:</u> 0203 7933588 - <u>email:</u> info@homesnag.co.uk



### GROUNDS

page	1
------	---

	MEETS STANDARDS	ACTION REQUIRED
HEALTH & SAFETY		<ul> <li>Pot holes presented a health and safety concern</li> <li>Trip hazards were evident, presenting a health and safety concern</li> </ul> Groundworkers to finish works in time for the homeowners occupation, ensuring there are no health and safety concerns of trip or falls from height.
SCAFFOLDING	Meets Standards ✓ There were no scaffolding around the immediate perimeter of property	
<b>GROUNDWORKS</b> Roads, Footpaths, Driveways, kerbs and steps		<ul> <li>There are uneven flags which present the possibility of rainwater pooling</li> <li>Groundworker to attend and rectify in time for occupation</li> </ul>
LAWN		<ul> <li>The turf is missing. We are unaware of whether this is provided as part of the sale</li> <li>See Works Ongoing / Limitations overleaf</li> </ul> Site to ensure that healthy turf is provided in time for occupation (if provided as part of the sale). Please ensure there is 100mm of topsoil, laid at a suitable time of year and does not waterlog.
TIDY SITE	Meets Standards ✓ The general environment was reviewed and considered acceptable.	
DRAINS	Meets Standards ✓ The inspection chambers were checked and there were no signs of standing water / debris, fixings were in tact and the chambers were level to ground	



### GROUNDS

### page 2

#### **ONGOING WORKS**



Fence not finished beside house



Ongoing works

#### LIMITATIONS

Some inspection chambers not readily accessible, site to check all are clear

#### **URGENT ISSUES**

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Gap in turf



Cement poor around chamber cover



Front garden not finished



Poor appearance gravel could get in mower



Slabs not level



### GARAGE

	MEETS STANDARDS	ACTION REQUIRED
GARAGE ROOF	Meets Standards ✓ Seen from ground level (as best as can be inspected), the garage roof meets standards.	
GARAGE FASCIAS & SOFFITS	Meets Standards ✓ The fascias / soffits / bargeboards were inspected and there were no issues identified	
GARAGE GUTTERS & DOWNPIPES	Meets Standards ✓ Seen from ground level (as best as can be inspected), the garage gutters and downpipes meets standards. We recommend inspecting after heavy rainfall.	
GARAGE WALLS		<ul> <li>The brickwork needs repointing</li> <li>See Works Ongoing / Limitations overleaf</li> </ul> Brickworker to repair / repoint the damage or section of wall as shown in the photos overleaf
GARAGE DOOR		<ul> <li>Door damage / scratched</li> <li>Joiner or Garage door company to rectify ideally before customer completes</li> </ul>
GARAGE FLOOR		• Screed is uneven Groundworker to attend and remedy screed so that it is evenly laid, flat but with a gradient toward the front so that any rainwater or flammable liquids exit.
GARAGE WINDOWS	The garage does not have any windows	



### GARAGE

page	4
------	---

	MEETS STANDARDS	ACTION REQUIRED
GARAGE SERVICES	Meet Standards ✓ The garage services were checked (visual check other than a basic test to sockets and switch operation) and were neat and in good working order	

#### **ONGOING WORKS**

### LIMITATIONS

**URGENT ISSUES** 

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Mortar cracked



Floor not smooth



Personnel door dented



Pests could enter gap above door, cover



Wall plate strap wonky



Membrane protrudes from brickwork



Mould on party wall



Mortar gaps around rafter tails



Firestop above wall loose, shouldn't be gaps



### ROOF



	MEETS STANDARDS	ACTION REQUIRED
MAIN ROOF		• The Canopy is damaged Roofer to replace section of roof that is damaged / not uniform etc
SOFFITS, FASCIAS ETC	Meets Standards ✓ The fascias / soffits / bargeboards have been checked and no issues were found	
GUTTERS & DOWNPIPES	Meets Standards ✓ Seen from ground level (as best as can be inspected), the garage gutters and downpipes meets standards. We recommend inspecting after heavy rainfall.	
CHIMNEY	N/A - no chimney	

PV PANELS	URGENT ISSUES
There are no PV panels present	
please note: this is a non technical check, we are just confirming presence	



### ONGOING WORKS

#### LIMITATIONS

PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Coping chipped, sand coat







Splitting around canopy



Paint damaged on canopy



Spacer protrudes behind bracket





# BOUNDARY & SERVICES

	MEETS Standards	ACTION REQUIRED
WALLS & FENCING		<ul> <li>See Works Ongoing / Limitations overleaf</li> <li>Gate fouls when operating</li> </ul> Fencing / brickworkwork / groundworkers to remediate so that the boundaries are complete in time for occupation
OUTDOOR BUILDINGS	N/A - there were no outdoor buildings (e.g. shed) at the time of inspection	
EXTRACTOR VENT	Meets Standards ✓ No issues were noted with the extractor fan vent	
FLUE VENT	Meets Standards ✓ No issues were noted with the flue vent	
METER BOXES		<ul> <li>The pipe / cables are not sealed</li> <li>Clip to the hockey stick is missing</li> </ul> Site to instruct relevant trade to complete finish of the meter box ensuring it is securely fixed level, with sealed pipes and cables.
CAR CHAR	GING POINT	AIR SOURCE HEAT PUMPS
There is no car cho	arger	There is no Air Source Heat Pump System present

please note: these are non technical checks, we are just confirming presence





### **BOUNDARY** & SERVICES

#### **ONGOING WORKS**

LIMITATIONS

**URGENT ISSUES** 

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Intumescent putty missing from gas pipe



Sealant missing around ground wire



Some bulbs missing



Gas pipe clip missing



Light off plumb



	MEETS STANDARDS	ACTION REQUIRED
BRICKWORK / RENDER / CLADDING / TILING	Meets Standards ✓ The elevations have been checked and they meet standards (plumb, straight and consistent in finish)	
DPC	Meets Standards ✓ The height of the DPC was considered fine, as much as it is possible to determine without intrusive check.	
EXPANSION JOINTS	Meets Standards ✓ The expansion joints (if present) were acceptably installed. Note: we are unable to determine the correct location or number of joints required.	
WEEP VENTS		• Weep vents damaged Brickworker to ensure there are sufficient weep vents that are undamaged and clean.
AIR BRICKS		<ul> <li>The air brick is too low. It should have at least one brick (75mm) clearance to ensure air flow and avoid rainwater ingress</li> <li>Brickworker to ensure air bricks are clear from ground level, clean and undamaged.</li> </ul>
FLASHINGS		• The flashing does not appear properly connected Mastic and/or brickworker to tidy appearance of flashing ensuring it is properly sealed, in line to cavity trays



### ELEVATIONS



#### **ONGOING WORKS**

#### LIMITATIONS

**URGENT ISSUES** 

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Weep vent damaged front corner



**Repoint around lintels** 



Mortar messy left of

garage

Cast stone damaged around fenestration



Hole on rear of garage

Sealant missing around pipe



Flashing not flush



Sticker on sill above front door



Air brick below ground level



page 11

	MEETS STANDARDS	ACTION REQUIRED
EXTERNAL		<ul> <li>Door furniture damage</li> <li>The door is damaged / scratched</li> </ul>
DOORS		Joiner to adjust or repair the door accordingly, ensuring it does not foul and has a consistent finish.
WINDOWS		• See Works Ongoing / Limitations overleaf
WINDOWS		Plastic surgeon to repair or glazing company to adjust / replace if required.
0 N G 0 I N G	WORKS	LIMITATIONS

& DOORS

**URGENT ISSUES** 



### page **12**

### WINDOWS & DOORS

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Patio hinge scuffed



Stubborn stains on sills




Scuffs on number





Caps missing from front door hinges



Weather bar end caps missing



Back door sill scratched



Front door sill deflects



Front door threshold not level



### HALLWAY



	MEETS STANDARDS	ACTION REQUIRED
DOOR	Meets Standards ✓ The door currently operates and does not appear to have any damage	
FLOOR		• Flooring is damaged Flooring contractor to address flooring levels and squareness to walls is not obvious and ensure any damage is replaced or repaired.
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS & CEILINGS	Meets Standards ✓ The walls and ceilings have been checked and are acceptably flat / plumb.	
WINDOWS		
LIGHTS, SOCKETS & SWITCHES	Meets Standards ✓ The sockets, switches and lights appear level and in working order.	
RADIATORS / UNDERFLOOR	Meets Standards ✓ The radiators appeared to all be working, undamaged and level.	



**ONGOING WORKS** 

### HALLWAY



### LIMITATIONS

**URGENT ISSUES** 

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Paint flashing on wall, repaint



Paint flashing on ceiling



Floor scratched nr front door



Make good around switches/sockets



Wrong paint used for touch ups



Touch up doors throughout house



## **DOWNSTAIRS WC**

page **15** 

	MEETS STANDARDS	ACTION REQUIRED
DOOR		• See Works Ongoing / Limitations overleaf Joiner to adjust / plastic surgeon to repair as required
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS & CEILINGS		• Wall is not straight Plasterer to attend and skim to take the eye off. Otherwise Site Manager to instruct trades to rectify.
RADIATORS / UNDERFLOOR		• The radiator isn't level Plumber to attend and appropriately repair
WINDOWS	Meets Standards / The Windows have been checked and they operate as intended and are not damaged	
SINK & PEDESTAL / VANITY		<ul> <li>The sink is not level</li> <li>Vanity not level</li> <li>vanity unequal gap</li> </ul> Plumber to attend to rectify / replace if required





page **16** 

	MEETS STANDARDS	ACTION REQUIRED
TOILET		<ul> <li>Toilet not secure</li> <li>Plumber to attend and rectify (replacing if necessary)</li> </ul>
SEALANT AROUND WET AREAS	Meets Standards ✓ Sealant around the wet areas was found to be full and neat.	
LIGHTS & EXTRACTION	Meets Standards ✓ The extractor fan and light appear in working order.	
SOCKETS & SWITCHES	Meets Standards ✓ Sockets and switches in the bathroom (if any) appeared in good order.	



### **DOWNSTAIRS WC**



# LIMITATIONS **ONGOING WORKS URGENT ISSUES**

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Wall not flat







>10mm gap below door



Paint blemish examples



Vanity unit distorted



## LIVING ROOM

page **18** 

	MEETS STANDARDS	ACTION REQUIRED
DOOR		• See Works Ongoing / Limitations overleaf Joiner to adjust / plastic surgeon to repair as required
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS & CEILINGS		• The Ceiling isn't flat (noticeably by eye) Plasterer to skim the area to take the eye off. Otherwise Site Manager to instruct works to rectify
WINDOWS	Meets Standards ✓ The Windows have been checked and they operate as intended and are not damaged	
LIGHTS, SOCKETS & SWITCHES		• The switches are not level and is obvious by eye Electrician to adjust and replace as required.
RADIATORS / UNDERFLOOR		• The radiator isn't level Plumber to attend and appropriately repair



### LIVING ROOM

PHOTO OF ROOM (IF NOT OBVIOUS)	LIMITATIONS
ONGOING WORKS	URGENT ISSUES

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Latch doesn't retreat against the strike plate



Ceiling not flat above door



Switch not level






Board join crack on ceiling



Ceiling not flat at inverted corner



Wrong paint used of skirting touch ups



# DINING AREA / ROOM

	MEETS STANDARDS	ACTION REQUIRED
DOOR		
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS & CEILINGS	Meets Standards ✓ The walls and ceilings have been checked and are acceptably flat / plumb.	
WINDOWS		
LIGHTS, SOCKETS & SWITCHES	Meets Standards ✓ The sockets, switches and lights appear level and in working order.	
RADIATORS / UNDERFLOOR	Meets Standards ✓ The radiators appeared to all be working, undamaged and level.	



# DINING AREA / ROOM

PHOTO OF ROOM (IF NOT OBVIOUS)	LIMITATIONS
ONGOING WORKS	URGENT ISSUES

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Make good around down lights



Paint flash on ceiling



# KITCHEN



	MEETS STANDARDS	ACTION REQUIRED
DOOR		• See Works Ongoing / Limitations overleaf Joiner to adjust / plastic surgeon to repair as required
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING & PLINTHS	Meets Standards ✓ The Skirting and plinths have been checked and appear undamaged and fitted properly	
WALLS & CEILINGS	Meets Standards ✓ The walls have been checked and are acceptably flat and plumb.	
WINDOWS	Meets Standards ✓ The Windows have been checked and they operate as intended and are not damaged	
LIGHTS, SOCKETS & SWITCHES	Meets Standards ✓ The extractor fan and light appear in working order.	
RADIATORS / UNDERFLOOR		



# KITCHEN



	MEETS STANDARDS	ACTION REQUIRED
UNIT DOORS & DRAWERS		<ul> <li>See Works Ongoing / Limitations overleaf</li> <li>Drawer is not aligned level / with uniform gap</li> </ul> Kitchen fitter to adjust / replace as required
APPLIANCES	Meets Standards ✓ Appliances appear damage free. Note: we are unable to determine whether a system fault.	
SINK & TAP		• The sink is scratched / damaged noticeably Plumber to fix / replace parts if required.
WORKTOP & HOB	Meets Standards ✓ The hob and worktop appear in good order as seen from 0.5m	
SEALANT	Meets Standards ✓ Sealant around the wet areas was found to be full and neat.	

#### **URGENT ISSUES**

Ideally there should be double check valve on pipe incase the appliance is change to one without one



### **KITCHEN**

### **ONGOING WORKS**

#### LIMITATIONS

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Paint missing above cupboards





Paint blemish example



Clean off paint



Clean off paint



Handle stiff



Make good below sill tile trim







Make good above boiler



>10mm gap below door



Scratches on draining board



## UTILITY



	MEETS STANDARDS	ACTION REQUIRED
DOOR		• The door is damaged Joiner to adjust / plastic surgeon to repair as required
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING	Meets Standards ✓ The Skirting and plinths have been checked and appear undamaged and fitted properly	
WALLS & CEILINGS	Meets Standards ✓ The walls have been checked and are acceptably flat and plumb.	
WINDOWS		
LIGHTS, SOCKETS & SWITCHES	Meets Standards ✓ The extractor fan and light appear in working order.	
RADIATORS / UNDERFLOOR	Meets Standards ✓ The radiators appeared to all be working, undamaged and level.	



### UTILITY



	MEETS STANDARDS	ACTION REQUIRED
UNIT DOORS & DRAWERS	Meets Standards ✓ The drawers and cupboards have been checked and they operate as intended and are free from damage	
APPLIANCES	Meets Standards ✓ Appliances appear damage free. Note: we are unable to determine whether a system fault.	
SINK & TAP		• See Works Ongoing / Limitations overleaf Plumber to fix / replace parts if required.
WORKTOP	Meets Standards ✓ The Worktop appears in good order as seen from 0.5m	
SEALANT	Meets Standards ✓ Sealant around the wet areas was found to be full and neat.	

### URGENT ISSUES

### No double check valve



### UTILITY

#### **ONGOING WORKS**

### LIMITATIONS

PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



No double check valve



Damage on back door



Make good around down lights



Plaster dint



# **STAIRS & LANDING**

	MEETS STANDARDS	ACTION REQUIRED
NEWEL POSTS, HANDRAILS		See Works Ongoing / Limitations overleaf
& SPINDLES		Joiner to repair or replace as required
FLOOR INC.		See Works Ongoing / Limitations overleaf
TREADS & RISERS		Joiner / carpet fitter to adjust as required
STRING &	Meets Standards ✓ The String & skirting has been checked and appears an undamaged continual surface. Note:	
SKIRTING	continual surface. Note: settlement cracks will occur along here.	
WALLS &	Meets Standards ✓ The walls and ceilings have been checked and are acceptably flat /	
CEILINGS	plumb.	
WINDOWS	Meets Standards ✓ The Windows have been checked and they operate as intended and	
WINDOWS	are not damaged	
LIGHTS, SOCKETS		The light fitting is not flush
& SWITCHES		Electrician to adjust and replace as required.
RADIATORS		See Works Ongoing / Limitations overleaf
		Plumber to attend and appropriately repair



ONGOING WORKS	LIMITATIONS
	UDGENT ISSUES

URGENTISSUES

Top nosing not level, trip hazard

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Radiator off bracket



Dent on newel post



Nosing not level



Switch is visibly not level




Make good fixing holes on caps



Light not flush



Make good handrail newel post joins



blemish on wall above corner of stairs



### MASTER BEDROOM

	MEETS STANDARDS	ACTION REQUIRED
DOOR	Meets Standards ✓ The door currently operates and does not appear to have any damage	
FLOOR		<ul> <li>Flooring is not reasonably level/flat (tangible underfoot or obvious by eye)</li> <li>Flooring contractor to address flooring levels and squareness to walls is not obvious and ensure any damage is replaced or repaired</li> </ul>
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS (INC. ANY WARDROBES) & CEILINGS		• There is damage to the wardrobe as seen from 0.5m Joiner / plasterer to rectify. Otherwise Site Manager to instruct necessary works to rectify
WINDOWS		<ul> <li>See Works Ongoing / Limitations overleaf</li> <li>Plastic Surgeon to repair or glazing company to replace as appropriate.</li> </ul>
LIGHTS, SOCKETS & SWITCHES	Meets Standards ✓ The sockets, switches and lights appear level and in working order.	
RADIATORS / UNDERFLOOR		• See Works Ongoing / Limitations overleaf Plumber to attend and appropriately repair



## MASTER BEDROOM

PHOTO OF ROOM IF NOT OBVIOUS	LIMITATIONS
ONGOING WORKS	URGENT ISSUES



Crack on ceiling



Blemish on wardrobe door



Screws missing from wardrobe door runner



Shouldn't be TRV on radiator



Pips missing from handles



Floor not level btwn door & middle of room



## MASTER ENSUITE

	MEETS STANDARDS	ACTION REQUIRED
DOOR	Meets Standards ✓ The door currently operates and does not appear to have any damage	
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS & CEILINGS		<ul> <li>See Works Ongoing / Limitations overleaf</li> <li>Plasterer to attend and skim to take the eye off. Otherwise Site Manager to instruct trades to rectify.</li> </ul>
WINDOWS		
LIGHTS, SOCKETS & EXTRACTION		• The fitting is not flush Electrician to adjust / replace as required.
RADIATORS / UNDERFLOOR	Meets Standards ✓ The radiators appeared to all be working, undamaged and level.	



## MASTER ENSUITE

	MEETS STANDARDS	ACTION REQUIRED
SINK & TAPS	Meets Standards ✓ The sink, taps and pedestal have been checked and they are level / square and work as intended	
PEDESTAL & VANITY		• Unequal gaps or unlevel installation of the vanity Plumber to attend to rectify / replace if required
		Toilet missing fixings
TOILET		Plumber to attend and rectify (replacing if necessary)
		The sealant is not neat / section missing around wet area
SEALANT AROUND WET AREAS		Mastic trade / plumber to renew so the sealant is continual and neat.
SHOWER / BATH	Meets Standards ✓ The shower / bath has been inspected including plumbing overflow (as best as can be inspected) and revealed no issues	

#### URGENT ISSUES



### **MASTER ENSUITE**

#### ONGOING WORKS


#### LIMITATIONS



#### Configure extractors throughout house



Caulk gap



Make good btwn tile trim and wall



Clip cable to wall



Uneven gap



Cap missing side of toilet



Tiling not straight corner of shower



Poor tile alignment 2mm deviation



Sealant missing below shower frame





### **BEDROOM 2**


	MEETS STANDARDS	ACTION REQUIRED
DOOD		• The door frame is distorted / has unequal gap
DOOR		Joiner to adjust / plastic surgeon to repair as required
FLOOR		There is excessive creaking
TEOOK		Flooring contractor to address flooring levels and squareness to walls is not obvious and ensure any damage is replaced or repaired.
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS, CEILINGS & ANY WARDROBES	Meets Standards ✓ The walls and ceilings (plus any inbuilt wardrobes if present) have been checked and are acceptable.	
		See Works Ongoing / Limitations overleaf
WINDOWS		Plastic Surgeon to repair or glazing company to replace as appropriate.
LIGHTS, SOCKETS & SWITCHES	Meets Standards ✓ The sockets, switches and lights appear level and in working order.	
RADIATORS		The radiator isn't level
/ UNDERFLOOR		Plumber to attend and appropriately repair





PHOTO OF ROOM IF NOT OBVIOUS	LIMITATIONS
ONGOING WORKS	URGENT ISSUES

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



Seal loose on window



>5mm door gap





Paint blemish examples



	MEETS STANDARDS	ACTION REQUIRED
DOOR	Meets Standards ✓ The door currently operates and does not appear to have any damage	
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS, CEILINGS & ANY WARDROBES	Meets Standards ✓ The walls and ceilings (plus any inbuilt wardrobes if present) have been checked and are acceptable.	
WINDOWS		• See Works Ongoing / Limitations overleaf Plastic Surgeon to repair or glazing company to replace as appropriate.
LIGHTS, SOCKETS & SWITCHES		• See Works Ongoing / Limitations overleaf Electrician to adjust and replace as required.
RADIATORS / UNDERFLOOR	Meets Standards ✓ The radiators appeared to all be working, undamaged and level.	





LIMITATIONS
URGENT ISSUES

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS





Seal loose

Outlet loose



	MEETS STANDARDS	ACTION REQUIRED
DOOR	Meets Standards ✓ The door currently operates and does not appear to have any damage	
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS, CEILINGS & ANY WARDROBES	Meets Standards / The walls and ceilings (plus any inbuilt wardrobes if present) have been checked and are acceptable.	
WINDOWS		• The window handle is tarnished Plastic Surgeon to repair or glazing company to replace as appropriate.
LIGHTS, SOCKETS & SWITCHES	Meets Standards ✓ The sockets, switches and lights appear level and in working order.	
RADIATORS / UNDERFLOOR	Meets Standards ✓ The radiators appeared to all be working, undamaged and level.	



### **BEDROOM 4**



PHOTO OF ROOM IF NOT OBVIOUS	LIMITATIONS
ONGOING WORKS	URGENT ISSUES





	MEETS STANDARDS	ACTION REQUIRED
DOOR	Meets Standards ✓ The door currently operates and does not appear to have any damage	
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS & CEILINGS		• There is a cracked / scratched tile Tiler to ensure tiles have a neat and tidy appearance, with undamaged tiles and even grout.
WINDOWS		
LIGHTS, SOCKETS & EXTRACTION		• The fitting is not flush Electrician to adjust / replace as required.
RADIATORS / UNDERFLOOR	Meets Standards ✓ The radiators appeared to all be working, undamaged and level.	



### BATHROOM

page	42
------	----

	MEETS STANDARDS	ACTION REQUIRED
SINK & TAPS		• The sink is not level
		Plumber to attend to rectify / replace if required
PEDESTAL		• Unequal gaps or unlevel installation of the vanity
& VANITY		Plumber to attend to rectify / replace if required
	Meets Standards ✓ The toilet has been checked and it functions, is damage free with soft	
TOILET	close.	
SEALANT AROUND	Meets Standards ✓ Sealant around the wet areas was found to be full and neat.	
WET AREAS		
SHOWER / BATH		

#### **URGENT ISSUES**

Shower head reaches toilet, backflow risk



### **BATHROOM**

### page 43

#### **ONGOING WORKS**

#### LIMITATIONS



Tiles chipped below shelf



Clip cable to wall



Plaster dint examples



Light not flush



Shower head reaches toilet



Poor finish by right end of bath



Basin off level



# AIRING CUPBOARD

	MEETS STANDARDS	ACTION REQUIRED
DOOR		• The door frame is distorted Joiner to adjust / plastic surgeon to repair as required
FLOOR	Meets Standards ✓ The flooring has been checked and it appears acceptably level when walked over & by eye	
SKIRTING	Meets Standards ✓ The Skirting has been checked and appears an undamaged continual surface	
WALLS & CEILINGS	Meets Standards ✓ The walls and ceilings have been checked and are acceptably flat / plumb.	
LIGHTS, SOCKETS & SWITCHES	Meets Standards ✓ The sockets, switches and lights appear level and in working order.	



### AIRING CUPBOARD

page **45** 

PHOTO OF ROOM IF NOT OBVIOUS	LIMITATIONS
ONGOING WORKS	URGENT ISSUES
	ORGENTISSUES

#### PHOTOS OF ISSUES THAT DO NOT MEET STANDARDS



>5mm door gap



LOFT



	MEETS STANDARDS	ACTION REQUIRED
НАТСН	Meets Standards ✓ The loft hatch was checked and was operating freely	
INSULATION	Meets Standards ✓ The insulation appeared to be cross laid and had ample coverage	
SOIL / VENT CONNECTIONS		<ul> <li>To ensure extract fans work effectively flexi ducting run should be a max of 1.5m</li> <li>Plumber to access and ensure soil pipes / extraction fans are properly installed</li> </ul>
CABLES	Meets Standards ✓ There were no obvious signs of loose cables	
TIMBERS	Meets Standards ✓ The timbers appear (at least to the immediate area around hatch) to be correctly installed.	
FELT / RAFTER BOARDS	Meets Standards ✓ The felt / rafter boarding appeared damage free	

Due to health and safety, a 'head and shoulders' check was carried out from the opening of latch hatch







URGENT ISSUES	LIMITATIONS



### HEATING



### ALARMS ETC



please note: these are non technical checks, we are just confirming presence